ADV2024_341 Cisco Security Advisory (7th October 2024)

Cisco has published a security advisory to address vulnerabilities affecting the following products on October 2, 2024. It is recommended that you take the necessary precautions to ensure your products are always protected.

- Cisco Meraki MX Firmware Release – version 16.2 and later, version 17.0 and later, version 18.0 and later
- Cisco NDFC – version 12.0
- Cisco RV340 Dual WAN Gigabit VPN Routers
- Cisco RV340W Dual WAN Gigabit Wireless-AC VPN Routers
- Cisco RV345 Dual WAN Gigabit VPN Routers
- Cisco RV345P Dual WAN Gigabit PoE VPN Routers

For more information on these updates, you can follow these URLs:

1. https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-meraki-mx-vpn-dos-QTRHzG2
2. https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-ndfc-cmdinj-UvYZrKfr#vp
3. https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-rv34x-privesc-rce-qE33TCms
4. https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-ndfc-ptrce-BUSHLbp

The Guyana National CIRT recommends that users and administrators review these updates and apply them where necessary.

References

- Cisco Security Advisories. (2024, October 2). Retrieved from Cisco. https://sec.cloudapps.cisco.com/security/center/publicationListing.x
- Cisco security advisory. (2024, October 2). Retrieved from Canadian Centre for Cyber Security. https://www.cyber.gc.ca/en/alerts-advisories/cisco-security-advisory-av24-557